



THE OFFICIAL NEWSMAGAZINE OF THE AMERICAN ACADEMY OF PEDIATRICS

AAP News

Volume 34 • Number 5
May 2013
www.aapnews.org

Health Alerts

The U.S. Consumer Product Safety Commission (CPSC) has announced the recall of the following products. Consumers should stop using recalled products unless otherwise instructed. Consumers can submit reports of harm to CPSC's new searchable online product safety database at www.SaferProducts.gov. A searchable food and medical product recall database is available at www.fda.gov/Safety/Recalls/default.htm.

Drop-side cribs

Units: About 73,000

Hazard: Part of the crib's drop side can fall out of position, creating a space into which an infant or toddler can roll and become trapped.

Description: Recalled are 14 models of PT Domusindo Perdana wooden drop-side crib: 343-1509 (Jenny Lind Crib, 01/1991-12/1997151), 343-3810 (Christopher Crib, 2001151), 343-5500 (Early American Crib, 01/1998-12/1999151), 343-6771 (Scottsdale Crib, 01/1998/12/1999151), 343-7100 (Sleigh Crib without Rosette, 01/2004-12/2006), 343-7134 (Sleigh Crib, 01/2001-2/2004), 343-7144 (Anniversary Sleigh Crib, 01/2002-12/2004), 343-7753 (Kristin Crib, 01/1998-12/1999), 343-8249 (Cameron Crib, 01/1998/12/1999), 343-8020 (Solid Panel Sleigh Crib, 01/2001-12/2002), 343-8070 (Roll Bar Convertible Crib, 01/2004-12/2005), 343-8155 (Anniversary Convertible Sleigh Crib, 01/2002-12/2006), 343-8200 (Spindle Convertible Crib, 01/2001-12/2005) and 343-8913 (Bella 3-in-1 Crib, 01/2005-12/2008).

Sold at: JCPenney.com and the JCPenney catalog from January 1998 through December 2008 for \$200 to \$400.

Remedy: Contact Modus Furniture International for a free kit that will immobilize the drop side.

Contact: Call 800-827-2129 or visit www.avannababy.com.

