

## Health Alerts

The U.S. Consumer Product Safety Commission (CPSC) has announced the recall of the following products. Consumers should stop using recalled products unless otherwise instructed. Consumers can submit reports of harm to CPSC's searchable online product safety database at [www.SaferProducts.gov](http://www.SaferProducts.gov). A searchable food and medical product recall database is available at [www.fda.gov/Safety/Recalls/default.htm](http://www.fda.gov/Safety/Recalls/default.htm).

### Bicycle release levers

Units: About 460

**Hazard:** An open quick release lever on the bicycle's front wheel hub can come into contact with the front disc brake assembly, causing the front wheel to come to a sudden stop or separate from the bicycle.

**Description:** The recalled products are all model year 2014 Huffy TR 745 and TR-S 740 bicycles with 27.5-inch wheels. "Huffy" is on the downtube of the frame of both bicycles, and model name TR 745 or TR-S 740 is on the rear portion of the frame. The TR 745 has a green frame with model number 26504M on the bottom of the frame near the pedals. The TR-S 740 has a white frame and model number 26604M on the bottom of the frame near the pedals. Bicycles that have a green dot on the inside of the quick release lever are not recalled.

**Sold at:** Walmart.com, Sears Puerto Rico and The Northwest Company (Cost U Less) from September 2014 through May 2015 for \$250 to \$370.

**Remedy:** Contact Huffy for a free replacement quick release lever for the front wheel.

**Contact:** Call 888-366-3828, email [Service@Huffy.com](mailto:Service@Huffy.com) or visit [www.huffybikes.com](http://www.huffybikes.com).

